



North Fork Tolt River Hancock Land Acquisition


Libraries and Utilities Committee
September 12, 2013

Location of Tolt Slide Area





LIDAR with Contours



Slide Timeline

- 1998 – Tolt Pipeline 2 constructed, road paved
- 2000 (spring) – First cracks in road appear
- 2000 (fall) – Rock buttress constructed
- 2001-06 – Area monitored; minor cracking and movement detected
- 2008 – Summer cracking observed for first time; Pipeline 1 leak discovered a few months later

Slide Timeline (2)

- 2009 (winter) – Larger road cracking and accelerated ground movement following large rain-on-snow event; Pipeline 2 damaged and repaired
- 2009 (summer) – TPL2 inspected, some damage found, Pipeline repaired and strengthened in Fall
- 2010 – Present – Continued monitoring, periodic pipeline inspections, geotechnical studies, and overall options analysis

Causes for Instability

- An ancient landslide that was relatively stable
- Original Tolt Pipeline remained tight for 50 years; if movement was like today it would have failed a few years after installation

“...it seems likely that some factor has tipped the balance towards slope instability in recent years...”

Causes for Instability

- **Groundwater** – what's changed recently?
- Uphill area logged in mid-1990
- One fir tree evaporates up to 10,000 gallons of water per year, say 5,000 gpy
- Assume 1,000 trees were removed
- Additional water load would be 5 MG per year, or 10 gpm

Slope movement accelerated significantly when TPL1 sprang a leak of 15-18 gpm

Hancock timber land acquisition

- Cost effective approach to mitigating future slide risk
- Low risk: SPU could sell property at likely profit in future
- Approx. 118.5 acres
- \$888,000 based on Uniform Standards of Professional Appraisal Practice (USPAP) appraisal